

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,092,794 B1
APPLICATION NO. : 09/679853
DATED : August 15, 2006
INVENTOR(S) : Mark Alexander Hill et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:


TITLE: METHOD AND APPARATUS FOR CONNECTING TO HVAC DEVICE

- i) in Column 6, Line 23. The reference to "said server" is incomplete and should be replaced with --said server; on demand in order to detect a problem associated with the monitoring of the at least one HVAC device as well as to detect any problems with the monitored device itself;--.
- ii) in Column 6, Line 55. The reference to "entry device" is incomplete and should be replaced with --entry device; on demand in order to detect a problem associated with the monitoring of the at least one HVAC device as well as to detect any problems with the monitored device itself;--.
- iii) in Column 8, Line 3. The reference to "status information; and" is incomplete and should be replaced with --status information; on demand in order to detect a problem associated with the monitoring of the at least one HVAC device as well as to detect any problems with the monitored device itself--.

This certificate supersedes Certificate of Correction issued November 14, 2006.

Signed and Sealed this

Second Day of January, 2007



JON W. DUDAS
Director of the United States Patent and Trademark Office